



## **Heavy Duty Vibration Meter**

Measures Acceleration, Velocity and Displacement

Stores the maximum and minimum values for later recall

## **Features:**

- Ranges Acceleration (peak): 656ft/s² (200m/s²),
  Velocity (peak): 7.87in/s (200mm/s),
  Displacement (peak-to-peak): 0.078in (2mm)
- Remote vibration sensor with magnetic adapter on 39"(1m) cable
- · Wide frequency range of 10Hz to 1kHz
- Resolution to 2ft/s² (0.5m/s²), 0.02in/s (0.5mm/s), and 0.001in (0.005)mm
- Basic accuracy of ±(5% + 2 digits)
- RMS or Peak Value measurement modes
- Manual/Auto store/recall up to 500 readings
- Data Hold freezes the reading in the display
- · Auto shut-off saves battery life
- 9V battery power or optional AC adaptor
- Dimensions: 7.1 x 2.8 x 1.3" (180 x 72 x 32mm);
  Weight with Probe: 0.87lbs (395g)
- Complete with remote sensor, magnetic mount, 9V battery, protective rubber holster with stand, and hard carrying case

## **Applications:**

- · Motors, bearings
- Fans
- Pumps
- Rotating machinery
- Plant maintenance



## **Ordering Information:**

